



- | | | | | |
|-------------------------|---------------------------|-------------------------|---------------------------|-------------------------|
| 11 16x
M6 | 12 4x
M6x65 | 13 4x
M6x60 | 14 4x
M6x50 | 15 8x
M6x35 |
| 16 4x
M6x20 | 17 12x
Ø5, 55 | 18 16x
Ø5, 20 | 19 2x | 20 20x
M6 |
| 21 2x | 22 12x
Ø4,8, 19 | 23 64x
Ø4, 15 | 24 8x
Ø4,8, 9,5 | 25 4x |
| 26 4x
M6x70 | 27 4x | 28 2x | 29 2x
M5x20 | 30 2x |
| 31 2x
R | 32 4x | 33 8x
Ø18, 2 | 34 4x
Ø18, β | 35 8x
Ø12, 16 |
| 36 2x
>105 | 37 2x
85 | 39 8x | 40 4x | 41 4x |
| 42 2x
Ø15, 25 | 43 8x | 44 6x
Ø4, 20 | 46 4x | 48 8x |